

# ***PIPING SOLUTIONS, INC.***

## IMPORTANT NOTE FOR WINDOWS VISTA USERS:

As of the release of the Windows Vista operating system, Microsoft has instituted some changes in the default permissions granted to users, especially with regard to folders located under the Program Files directory. The default location of PipingSolutions programs is in this directory and depending on how permissions are set, you may not have access to the complete functionality of the software. **You may choose to save the program under C:\TRIFLEX.** If you accept the default installation location, in order to run PipingSolutions' software you must establish FULL CONTROL permissions for the C:\Program Files\PipingSolutions folder and all sub folders. This allows our programs to access and modify material and piping component data bases as well as to create, read, and delete temporary data files for transfer of information between the various executables. While some of these problems may be minimized when using a custom folder for installation, we recommend that even in this case, you verify that you have FULL CONTROL of the folder in which PipingSolutions' programs are installed.

In addition, you should verify that any folder used for storage of data files used in the programs have FULL CONTROL permissions set.

The modification of permissions for a folder generally requires administrative rights. These permissions may be set by right clicking on the folder in Windows Explorer, selecting the 'Properties' menu item, then the 'Security' tab.

Thank you,

The PipingSolutions Development Team



***PIPING SOLUTIONS, INC.*** *Houston, Texas*